



Newly Constructed 2 Storey Office Building

For Lease

705 Arlington Park Place, Kingston, On

©2024 Rockwell Commercial Real Estate Brokerage Corp. Independently owned and operated. Also operating as Rockwell Commercial Real Estate, Brokerage. All rights are reserved. No representation or warranty, express or implied, is made as to the accuracy or completeness of the information contained herein, and same is submitted subject to errors, omissions, change of price, rental or other conditions, withdrawal without notice, and/or to any special listing conditions imposed by the property owner(s). No representation or warranty is made with respect to the condition any real property or properties.

V241015



**Rockwell Commercial
Real Estate, Brokerage**
78 Brock St Kingston, ON K7L 1R9
www.rockwellcre.com

Property Details

Building Rentable Area	± 15,596.5 sf	
Ground Floor Suite(s) Available:	Suite 102	± 1,568.86 sf
	Suite 103	± 1,733.41 sf
	Suite 104	± 1,421.65 sf
Second Floor Suite(s) Available:	Suite 202	± 3,771.55 sf
Net Rental Rates:	Ground Floor: \$15.00 psf Second Floor: \$13.00 psf	
2025 Budgeted Additional Rent:	\$9.95 psf (including property taxes, operating costs and utilities)	
Fibre Optics	Bell Canada	
Landlord:	1000324626 Ontario Ltd.	
Parking:	Total of 49 on-site stalls plus 2 loading stalls (1 stall/318ft)	
Project Pylon Signage:	Landlord installing common pylon signage. Each tenant will have one space on sign.	
Leasehold Improvements:	Landlord will consider paying for leasehold improvement costs and amortizing those costs over initial lease term for financially qualified tenant and with appropriate indemnification, if required.	


Zoning

M2-E146 allowing for **office use** and accessory retail² use.

²Is permitted only as an accessory use to a principal use on the lot and is limited to a maximum gross floor area of 25% of the gross floor area of the principal use.

Landlord's Base Building


- Perimeter drywall finish (taped, sanded, ready for Tenant's paint);
- Sprinkler heads installed and dropped based on open floor plan;
- Cold water supply with shut-off to Premises;
- Communications conduit from demarcation room to Premises with pull-string;
- Adequate HVAC brought to Premises but not distributed;
- Adequate electrical brought to Premises with circuit breaker panel sized to meet tenant's requirements;
- Building Standard window covering installed (Melrose window coverings - Roller blinds with 3% openness square matte finish);
- Building standard suite entrance including 8 foot wood door & frame with hardware installed;
- Smooth level concrete floor ready for Tenant's finishes, and;
- Broom swept clean.




Highlights

- Newly constructed office building available, located 4kms south of Highway 401, with access off of Gardiners Road. Ideally located, in Kingston's west end, providing easy access to Kingston's major arterial thoroughway's and major cities along the Highway 401 corridor.
- Building Tenants include: Tarnowecky Law and Sutton Group - Masters Realty
- Within very close proximity to The Cataraqui Centre, Invista Centre RIOCAN Centre - including but not limited to the following tenants: Food Basics, Starbucks, Staples, Scotia Bank, TD Bank, Montana's BBQ & Bar, Freshii and much more.


Ground Floor



Second Floor



Site Plan



For Lease

705 Arlington Park Place, Kingston, On

Contact Information

Martin L. Skolnick
Broker/Vice President
+1 613 542-2724
martin.skolnick@rockwellcre.com



Rockwell Commercial Real Estate, Brokerage
78 Brock St. Kingston, ON K7L 1R9
www.rockwellcre.com

©2024 Rockwell Commercial Real Estate Brokerage Corp. Independently owned and operated. Also operating as Rockwell Commercial Real Estate, Brokerage. All rights are reserved. No representation or warranty, express or implied, is made as to the accuracy or completeness of the information contained herein, and same is submitted subject to errors, omissions, change of price, rental or other conditions, withdrawal without notice, and/or to any special listing conditions imposed by the property owner(s). No representation or warranty is made with respect to the condition any real property or properties.

V240517

Rockwell
COMMERCIAL